


09/2411-

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

2/60



[The page contains faint, illegible markings or bleed-through from the reverse side.]

FIG. 3




FIG. 4A





FIG. 4B



2025 RELEASE

FIG. 5A




FIG. 5B





FIG. 8



10/60

66000-1511500

FIG.10




FIG. 11




FIG. 12




FIG. 13





FIG. 14



This cross-sectional view shows a substrate 12 with a top surface 14 and a bottom surface 18. A dashed line 20 indicates an interface. Three circular features 70 are embedded in the substrate. Each feature 70 is surrounded by a ring of material 102. A layer 22 is deposited over the top surface 14, covering the features 70 and the rings 102. The layer 22 has a thickness 224. The substrate 12 is shown with a hatched pattern, and the layer 22 is shown with a dotted pattern.

FIG. 16




FIG.17




FIG.18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 25




FIG. 26A




FIG. 26B




FIG. 26C




FIG. 27A




FIG. 27B





FIG. 27C



66744-1

FIG. 28A




FIG. 28B




FIG. 28C




FIG. 29




FIG. 30




FIG. 31

FIG. 31




FIG. 32A




FIG. 32B




FIG. 32C




FIG. 32D




FIG. 33A




FIG. 33B




FIG. 33C





FIG. 34



66E00-15T4E60

FIG. 35




FIG. 36




FIG. 37




FIG. 38A




FIG. 38B




FIG. 39A




FIG. 39B




FIG. 39C




FIG. 39D




FIG. 40A





FIG. 40B



don't know why,
but replaced implem
12/1/02

FIG. 41A




FIG. 41B




FIG. 41C




FIG. 42A




FIG. 42B




FIG. 42C




FIG. 43A




FIG. 43B




FIG. 44A




FIG. 44B




FIG. 44C




FIG. 46A




FIG. 46B




FIG. 46C




FIG. 47A




FIG. 47B




FIG. 48




FIG. 49A




FIG. 49B




FIG. 49C




FIG. 53A




FIG. 53B




FIG. 53C




FIG. 54A




FIG. 54B




FIG. 55A




FIG. 55B




FIG. 55C




FIG. 56A




FIG. 56B




FIG. 57A




FIG. 57B





FIG. 57C



54/60

FIG. 58A





FIG. 58B



55/60-EE4E60

FIG. 59A




FIG. 59B




FIG. 59C




FIG. 60A






FIG. 60B



667000-164660

FIG. 61A



4/c

FIG. 62B




FIG. 62A




FIG. 62B

